

FIG. 1




FIG. 2




FIG. 3

140 MEMBER'S NUMBER	141 WHERE TO MAKE CONTACT	142 PRODUCTION NUMBER	143 PART	144 PRODUCTION DATE	145 VALUE	146 STATUS	147 RISK
001	TOKYO, A-CITY, B-TOWN	AAY9424678	COOLING WATER	1994-7-20	95°C	ABNORMAL	B
			ENGINE OIL	2000-1-25		GOOD	NO
			BRAKE PAD	2000-1-25	5mm	DETERIO- RATED	A
			SPEED CHANGER	1994-7-20		GOOD	NO
		BCZ9851001	COOLING WATER	1998-12-15		GOOD	NO
			ENGINE OIL	2000-1-25		GOOD	NO
			BRAKE PAD	2000-1-25		GOOD	NO
			SPEED CHANGER	1998-12-15		GOOD	NO
002	TOKYO, C-WARD, D	DDW9907005	COOLING WATER	1999-2-10		GOOD	NO
			ENGINE OIL	1999-2-10		GOOD	NO
			BRAKE PAD	1999-2-10		GOOD	NO
			SPEED CHANGER	1999-2-10		GOOD	NO
003	IBARAKI- PREFECTURE, E-CITY, F-TOWN	EEW7717125	COOLING WATER	1998-12-15		GOOD	NO
			ENGINE OIL	2000-1-25	200cc	DETERIO- RATED	C
			BRAKE PAD	2000-1-25	8mm	DETERIO- RATED	C
			SPEED CHANGER	1998-12-15		DETERIO- RATED	C

FIG. 4

4 / 21

MEMBER'S NUMBER NUMBER'S NAME		WHERE TO MAKE CONTACT	PRODUCTION NUMBER	PART	PART- EXCHANGED DATE	MAIN CAUSE	STATUS
001 KAI IN	ICHIRO	TOKYO, A-CITY, B-TOWN	AAY9424678	ENGINE OIL	1994-7-20	CAR SAFETY INSPECTION CAR SAFETY INSPECTION	DETERIO- RATED DETERIO- RATED
				BRAKE PAD	1994-7-20		
				SPEED CHANGER	1995-5-15	TRouble	ABNORMAL
				FRONT PANEL	1995-9-30	ACCIDENT	ABNORMAL
				FRONT GRASS	1995-9-30	ACCIDENT	ABNORMAL
				ENGINE	1995-9-30	ACCIDENT	ABNORMAL
				ENGINE OIL	1996-7-15	CAR SAFETY INSPECTION	DETERIO- RATED
				BRAKE PAD	1996-7-15	CAR SAFETY INSPECTION	DETERIO- RATED
				BATTERY	1996-7-15	CAR SAFETY INSPECTION	DETERIO- RATED
						====	====
						====	====

102

FIG. 5

160 COMPANY'S NUMBER COMPANY'S NAME	161 PLACE WHERE TO MAKE CONTACT	162 COMPANY'S HOLIDAY	163 BUSINESS TIME	164 DISTINCTIVE MARK
001 A SOBI K.K.	TOKYO, A-CITY, B-TOWN 03-xxxx-xxxx	WEDNESDAY	9:00-17:00	ONE-DAY CAR INSPECTION USER CAR INSPECTION SERVICE
002 B DEALER Y.K.	TOKYO, C-WARD, D 03-xxxx-xxxx	SUNDAY, PUBLIC HOLIDAY	9:00-19:00	TRADE-IN ASSESSMENT
003 C SEIBI K.K.	IBARAKI PREFECTURE, E- CITY, F-TOWN 029-zzz-zzzz	TUESDAY	7:00-16:00	ONE-DAY CAR INSPECTION

130

FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10








FIG. 11**FIG. 12**

SERVER COMPUTER

100

FIG. 13**FIG. 14**





FIG. 17




FIG. 18




FIG. 19




FIG. 20






FIG. 21**FIG. 23**


FIG. 22



FIG. 24**FIG. 25**



FIG. 26**FIG. 28**

FIG. 27




FIG. 29